

M223 Series Application Guide – Speed & Feed (inch)

ISO Code	Work Material	Type of Cut	Axial DOC	Radial DOC	Number of Flutes	Speed (SFM)	Feed (Inch per Tooth)							
							1/8	3/16	1/4	3/8	1/2	5/8	3/4	1
N	Aluminum Alloys 6061, 7075, 2024	Slotting	1 x D	1 x D	3	800	.0015	.0030	.0038	.0045	.0060	.0075	.0090	.0120
		Peripheral - Rough	≤ 2 x D	.5 x D	3	1000	.0020	.0040	.0050	.0060	.0080	.0100	.0120	.0160
		Peripheral - Rough	> 2 - 3 x D	.5 x D	3	1000	.0019	.0038	.0047	.0056	.0075	.0094	.0113	.0150
		Peripheral - Rough	> 3 - 4 x D	.45 x D	3	900	.0016	.0033	.0041	.0049	.0065	.0081	.0098	.0130
		Peripheral - Rough	> 4 - 5 x D	.4 x D	3	800	.0015	.0029	.0036	.0044	.0058	.0073	.0087	.0116
		Finish	2.5 x D	.015 x D	3	1200	.0007	.0014	.0017	.0020	.0027	.0034	.0041	.0054
		*Helical Ramp Angle	3.0 deg.	1 x D	3	800	.0012	.0024	.0030	.0036	.0048	.0060	.0072	.0096
	High Silicon Aluminum A380, A390	Slotting	.75 x D	1 x D	3	500	.0011	.0023	.0028	.0034	.0045	.0056	.0068	.0090
		Peripheral - Rough	≤ 2 x D	.4 x D	3	700	.0014	.0029	.0036	.0043	.0057	.0071	.0086	.0114
		Peripheral - Rough	> 2 - 3 x D	.4 x D	3	700	.0014	.0028	.0034	.0041	.0055	.0069	.0083	.0110
		Peripheral - Rough	> 3 - 4 x D	.375 x D	3	600	.0012	.0024	.0030	.0036	.0048	.0060	.0072	.0096
		Peripheral - Rough	> 4 - 5 x D	.35 x D	3	500	.0010	.0020	.0025	.0030	.0040	.0050	.0060	.0080
		Finish	2.5 x D	.015 x D	3	900	.0006	.0013	.0016	.0019	.0025	.0031	.0038	.0050
		*Helical Ramp Angle	2.5 deg.	1 x D	3	500	.0009	.0018	.0023	.0027	.0036	.0045	.0054	.0072
	Magnesium Alloys	Slotting	1 x D	1 x D	3	800	.0015	.0030	.0038	.0045	.0060	.0075	.0090	.0120
		Peripheral - Rough	≤ 2 x D	.5 x D	3	1000	.0020	.0040	.0050	.0060	.0080	.0100	.0120	.0160
		Peripheral - Rough	> 2 - 3 x D	.5 x D	3	1000	.0019	.0038	.0047	.0056	.0075	.0094	.0113	.0150
		Peripheral - Rough	> 3 - 4 x D	.45 x D	3	900	.0016	.0033	.0041	.0049	.0065	.0081	.0098	.0130
		Peripheral - Rough	> 4 - 5 x D	.4 x D	3	800	.0015	.0029	.0036	.0044	.0058	.0073	.0087	.0116
		Finish	2.5 x D	.015 x D	3	1200	.0007	.0014	.0017	.0020	.0027	.0034	.0041	.0054
		*Helical Ramp Angle	3.0 deg.	1 x D	3	800	.0012	.0024	.0030	.0036	.0048	.0060	.0072	.0096
	Copper Alloys, Brass	Slotting	.75 x D	1 x D	3	500	.0009	.0019	.0023	.0028	.0037	.0046	.0056	.0074
		Peripheral - Rough	≤ 2 x D	.4 x D	3	600	.0012	.0023	.0029	.0035	.0046	.0058	.0069	.0092
		Peripheral - Rough	> 2 - 3 x D	.4 x D	3	600	.0011	.0023	.0028	.0034	.0045	.0056	.0068	.0090
		Peripheral - Rough	> 3 - 4 x D	.375 x D	3	500	.0010	.0020	.0024	.0029	.0039	.0049	.0059	.0078
		Peripheral - Rough	> 4 - 5 x D	.35 x D	3	450	.0008	.0017	.0021	.0025	.0033	.0041	.0050	.0066
		Finish	2.5 x D	.015 x D	3	650	.0005	.0011	.0013	.0016	.0021	.0026	.0032	.0042
		*Helical Ramp Angle	2.5 deg.	1 x D	3	500	.0007	.0015	.0019	.0022	.0030	.0037	.0044	.0059
Bronze	Slotting	.75 x D	1 x D	3	500	.0009	.0018	.0022	.0026	.0035	.0044	.0053	.0070	
	Peripheral - Rough	≤ 2 x D	.4 x D	3	600	.0011	.0022	.0028	.0033	.0044	.0055	.0066	.0088	
	Peripheral - Rough	> 2 - 3 x D	.4 x D	3	600	.0011	.0021	.0026	.0032	.0042	.0053	.0063	.0084	
	Peripheral - Rough	> 3 - 4 x D	.375 x D	3	500	.0009	.0018	.0022	.0026	.0035	.0044	.0053	.0070	
	Peripheral - Rough	> 4 - 5 x D	.35 x D	3	450	.0007	.0015	.0018	.0022	.0029	.0036	.0044	.0058	
	Finish	2.5 x D	.015 x D	3	650	.0005	.0010	.0012	.0014	.0019	.0024	.0029	.0038	
	*Helical Ramp Angle	2.0 deg.	1 x D	3	500	.0007	.0014	.0018	.0021	.0028	.0035	.0042	.0056	
Composites, Plastic, Fiberglass	Slotting	.75 x D	1 x D	3	500	.0011	.0023	.0028	.0034	.0045	.0056	.0068	.0090	
	Peripheral - Rough	≤ 2 x D	.4 x D	3	700	.0014	.0029	.0036	.0043	.0057	.0071	.0086	.0114	
	Peripheral - Rough	> 2 - 3 x D	.4 x D	3	700	.0014	.0028	.0034	.0041	.0055	.0069	.0083	.0110	
	Peripheral - Rough	> 3 - 4 x D	.375 x D	3	600	.0012	.0024	.0030	.0036	.0048	.0060	.0072	.0096	
	Peripheral - Rough	> 4 - 5 x D	.35 x D	3	500	.0010	.0020	.0025	.0030	.0040	.0050	.0060	.0080	
	Finish	2.5 x D	.015 x D	3	900	.0006	.0013	.0016	.0019	.0025	.0031	.0038	.0050	
	*Helical Ramp Angle	3.0 deg.	1 x D	3	500	.0009	.0018	.0023	.0027	.0036	.0045	.0054	.0072	

*Straight-Line Ramp Angle = Helical Ramp Angle x 5 for entry up to 1 x D.

≈ Approximately Equals
 ≤ Less Than or Equal To
 ≥ Greater Than or Equal To
 × Multiply
 < Less Than
 > Greater Than
 = Equals

Common Machining Formulas

$$RPM = \frac{SFM \times 3.82}{D}$$

$$SFM = RPM \times D \times .262$$

$$IPM = RPM \times IPT \times Z$$

$$MRR = RDOC \times ADOC \times IPM$$

$$RPM = \frac{M/min \times 318.3}{D}$$

$$M/min = RPM \times D \times .00314$$

$$MMPM = RPM \times MMPT \times Z$$

$$MRR = RDOC \times ADOC \times MMPM$$

